




## SCHOOL BUILDING SAFETY CERTIFICATE

The building of Green Field Sr. Sec. School V.P.O. Chahri ( Nagrota Bagwan ) in Tehsil Nagrota Bagwan in Distt. Kangra (H.P) was inspected by the concerned Junior Engineer on dated 18-01-2023. As per the report of Junior Engineer this building has neither been designed nor been constructed by this department/office. No earth quake resistant norms have been adopted for this building. No structural drawings approved by the competent Govt. agency have been produced. The structure is a Non-Engineered structure, hence the structure safety of this building cannot be ensured specifically from earth quake point of view. This department will not be responsible for any type of loss of property etc. if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe at present only. This certificate is valid for academic session 2023-24. Fee amounting to Rs. 1,500/- only has been deposited vide GR No. 1517112 dated 18-01-2023.

Place: - Nagrota Bagwan.

  
Junior Engineer,  
Nagrota Sub-Division,  
HP.PWD Nagrota Bagwan.

  
Assistant Engineer,  
Nagrota Sub-Division,  
HP.PWD Nagrota Bagwan.

C/S  
  
Executive Engineer,  
HP.PWD Division,  
Tanda at Nagrota Bagwan

